

Spray Can/Bottle Holder

Installation and Usage Instructions

Please read instructions carefully and fully before installation and/or usage.



1 Open the hook & loop flap on the bottle holder and insert the bottle or can through the opening and let the top of the bottle protrude through the top. Once installed make any final adjustments for a proper fit and close the flap.



2 When wearing, use the carabiner mounted on the upper Dee Ring to install on an anchor point such as a Dee Ring on a belt.



3 When using the bottle or can, disconnect the carabiner from the anchor point without removing it from the Dee Ring on the bottle holder. When finished reinstall on to the anchor point



4 When using the optional coil lanyard, one end should be attached to the lower Dee Ring and the other end attached to an anchor point such as a Dee Ring on a belt.



5 If using the optional Cap Tether Kit follow the instructions on page 2 to install the adhesive tether loop on to the cap. Release the rope side of the MPC connector and cinch the strap to the upper Dee Ring and then reattach the rope side of the connector. When using the adhesive tether loop on a small cap, trimming the adhesive tether loop to fit the cap properly is acceptable to do.

IMPORTANT NOTES

- Dispose of if a drop is experienced
- Inspect prior to each use for the following and discard if found:
 - Degraded stitching, hook and loop
 - Rips or tears
 - Worn or loose parts are noted.
- Always install tools in a safe location as a precaution should a tool drop during installation.

PARTS LIST

PART NO.	ADDITIONAL PARTS NEEDED
HLDRBCSM	N/A
HLDRBCSMLNY	CC3325NPPL
HLDRBCLG	N/A
HLDRBCLGLNY	CC3325NPPL
HLDRBCKIT	1 TETHCNCHLP, 1 TL-ADH, 1 MPC

WARNINGS

ALWAYS WEAR APPROPRIATE PROTECTIVE EQUIPMENT. DO NOT USE THIS PRODUCT ON OR NEAR ROTATING EQUIPMENT. IMPROPER USE COULD RESULT IN DEATH OR DISMEMBERMENT. IF ANY CRACKS, RIPS OR TEARS NOTED, PRODUCT REPLACEMENT IS REQUIRED.



Ty-Flot, Inc. • 305 Massabesic Street • Manchester, NH 03103
www.ty-flot.com • Phone: 603-669-5169 • Fax: 603-669-5113

THE DROP STOPS HERE

INSTALLATION

Adhesive Attachment

Installation and Usage Instructions

Please read instructions carefully and fully before installation and/or usage.



IMPORTANT INFORMATION

- Adhesive tape is good for polycarbonate, nylon, PPE, acrylic, rigid PVC, ABS, aluminum, galvanized steel, stainless steel, glass, enameled steel, epoxy paint. Tape temp range is between -35°C to 90°C.

WEIGHT LIMITS

ATTACH TO	TLADH	TLADH-HD
RETRPBH Radio Pouch	1.0 lbs	1.5 lbs
CC5PHSNP Coil Lanyard	1.0 lbs	1.5 lbs
RETACCSM and LG Series Accessory Pouches (Front 30" Pocket)	1.5 lbs	2.0 lbs
12" Tethers	12 oz.	1.5 lbs
HLDR-BC-KIT Water Bottle Cap Kit	1.0 lbs	1.0 lbs

NOTE: FOR MAXIMUM BOND STRENGTH, THE SURFACES SHOULD BE CLEANED WITH A 50:50 MIXTURE OF ISOPROPYL ALCOHOL AND WATER. IDEAL TAPE APPLICATION IS ACCOMPLISHED WHEN THE TEMPERATURE IS BETWEEN 70°F AND 100°F (21°C AND 38°C).

TLADH Series



1 Peel and remove the white side of adhesive strip and attach it to the flat side of the TL-ADH plastic tether loop.



2 Select a flat, non-porous location on the device needing to be tethered and adhere the other side of the strip to the device. Allow 72 hours for maximum strength bond.

TLADH-HD Series



1 Peel and remove the adhesive strip and attach it to the flat side of the product being used.



2 Select a flat, non-porous location on the device needing to be tethered and adhere the other side of the strip to the device. Allow 72 hours for maximum strength bond.



Ty-Flot, Inc. • 305 Massabesic Street • Manchester, NH 03103
www.ty-flot.com • Phone: 603-669-5169 • Fax: 603-669-5113

THE DROP STOPS HERE